



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 1-23-09 Operator BP America API # 30-045-32081
Property Name Ludwick LS Well No. 15N Location: Unit 7 Section 19 Township 30 Range 10
Well Status (Shut-In or Producing) Initial PSI: Tubing 70 Intermediate 60 Casing 72 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min					77
10 min					80
15 min					80
20 min					80
25 min					82
30 min					82

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		light
Surges		
Down to Nothing		
Nothing		
Gas		
Gas & Water		RCVD JAN 23 '09
Water		OIL CONS. DIV.

If bradenhead flowed water, check all of the descriptions that apply below:

DIST. 3

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0 INTERMEDIATE 0

REMARKS:

BH nothing when opened.
that blew head & lighter in 40 seconds surged then
down to light blow in 2 minutes - light just 30 minutes

By Ray Jodasma
(Position) Tech

Witness Monica Quehnan
light blow when
opened after
5 min -
Latest in 4 months
(Man)

E-mail address _____