



NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170
www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test: 1/29/2009

Operator: Merrion Oil & Gas API #: 30-045-30271

Property Name: Flush Well No.: 1 Location: Unit: A Section: 2 Township: 26N Range: 13W

Well Status (Shut-In or Producing) Producing Tubing 0 Intermediate 11/1 Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:		
	BRADENHEAD	INTERMEDIATE	CASING
5 minutes			
10 minutes			
15 minutes			
20 minutes			
25 minutes			
30 minutes			

	BRADENHEAD FLOWED	INTERMEDIATE FLOWED
Steady Flow		
Surges		
Down to Nothing		
Nothing		
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:

Blew down in 4 seconds

By

Phelana Thompson

Witness

Monica Luchino

Regulatory
(Position)

E-mail address

pthompson@merrion.bz