

Bearcat Drilling

5424 US Highway 64
Farmington, NM 87401

PO BOX 717
Farmington, NM 87499

Phone: 505-327-5218
Fax: 505-564-9185

JAECO

Deviation Report


JAECO 28-3 #8

10/28N/3W

218'	.25		
779'	.42	3779'	1.0
1312'	1.00	4181'	.5
1780'	1.00	4624'	2.02
2279'	.5	5165'	1.99
2779'	1.0	5608'	1.28
3279'	1.25	6116'	1.73

Remainder of hole to TD was drilled with air


Surveys as reported by Bearcat Drilling Rig #5, Daily IADC Drilling Report.



Aaron Maurer – Bearcat Drilling

The State of New Mexico, County of San Juan

The foregoing instrument was acknowledged before me on this 12th day of February 2009



By Michelle DeAnne Brawley
Notary Public

My Commission Expires June 7th 2009

30-039-30004

RCVD FEB 12 '09

OIL CONS. DIV.

DIST. 3

46