



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

MECHANICAL INTEGRITY TEST REPORT

(TA OR UIC)

Date of Test 3-5-09 Operator Burlington Res. API # 30-0-39-24518

Property Name San Juan 306 LH Well # 2 Location: Unit 1 Sec 23 Twn 30 Rge 7

Land Type:

State
Federal /
Private
Indian

Well Type:

Water Injection
Salt Water Disposal /
Gas Injection
Producing Oil/Gas
Pressure observation

Temporarily Abandoned Well (Y/N): TA Expires:

Casing Pres. 0
Bradenhead Pres. 0
Tubing Pres. 34
Int. Casing Pres. N/A

Tbg. SI Pres.
Tbg. Inj. Pres.

Max. Inj. Pres.

RCVD MAR 5 '09
OIL CONS. DIV.
DIST. 3

Pressured annulus up to 520 psi. for 30 mins. Test passed failed

REMARKS:

Packer set at 7831
top of 2971 - 8862

dropped 15 pounds in 30 minutes

By Barton Fung COPC
(Operator Representative)

Witness Monica Luchling
(NMOCD)

(Position)

Revised 02-11-02

