



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/district.htm](http://emnr.state.nm.us/ocd/District%20III/district.htm)

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

Date of Test 4-7-09 Operator Manana Gas API #30-0 30045-32012

Property Name Cracked Seams Well No. 1 Location: Unit P Section 14 Township 30 Range 12

Well Status(Shut-In or Producing) Tubing 30 Intermediate Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	INTERMEDIATE	CASING		
5 minutes		<u>0</u>	Steady Flow	
10 minutes		<u>0</u>	Surges	
15 minutes		<u>0</u>	Down to Nothing	
20 minutes		<u>0</u>	Nothing	
25 minutes			Gas	
30 minutes			Gas & Water	
			Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

RCVD APR 16 '09

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE

OIL CONS. DIV.

DIST. 3

REMARKS:

By Ed Borch

Witness

Switcher
(Position)