



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/district.htm](http://emnr.state.nm.us/ocd/District%20III/district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5-6-09 Operator Chevron API #30-0 45-33440

Property Name Wilmerding 9 Well No. #3 Location: Unit C Section 10 Township 31 Range 13

Well Status (Shut-In or Producing) Initial PSI: Tubing None in hole Intermediate NA Casing 0 Bradenhead 16

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	<u>16</u>	<u>NA</u>	<u>0</u>		
10 min	<u>18</u>	<u>1</u>	<u>0</u>		
15 min	<u>18</u>		<u>0</u>		
20 min	<u>18</u>		<u>0</u>		
25 min	<u>20</u>		<u>0</u>		
30 min	<u>20</u>		<u>0</u>		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow <u>Soft Blow to touch</u>	
Surges	<u>RCVD MAY 6 '09</u>
Down to Nothing	<u>OIL CONS. DIV.</u>
Nothing	<u>DIST. 3</u>
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 19 INTERMEDIATE NA

REMARKS:

BH valve 2" soft blow to touch
No tubing in hole due to rig
csg dead / no pressure

By John Peterson
Well Site Manager
(Position)

Witness Richard Thoman

E-mail address _____