

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 5-19-09 Operator Dugan Production Corp. API # 30-045-23358
Property Name DOME OLD TRDG POST Well No 2 Location Unit A Section 15 Township 26N Range 14W
Well Status(Shut-In or Producing) Initial PSI: Tubing 0 Intermediate N/A Casing 78 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

TIME	Bradenhead			Interm		
	BH	Int	Csg	Int	Csg	
5 minutes	0		78			
10 minutes	0		78			
15 minutes	0		78			
20 minutes						
25 minutes						
30 minutes						

Steady Flow
Surges
Down to Nothing
Nothing
Gas
Gas & Water
Water

FLOW CHARACTERISTICS

BRADENHEAD	INTERMEDIATE
Nothing	N/A

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN

BRADENHEAD

INTERMEDIATE

REMARKS.

By

Paul J. M. #97
Switcher
(Position)

Witness

