

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6176

[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 5-12-09 Operator Dugan Production Corp. API # 30-045-31731
Property Name MAYRE Well No. 90S Location: Unit I Section 31 Township 30N Range 14W
Well Status(Shut-In or Producing) Initial PSI: Tubing 0 Intermediate 0 Casing 8 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE						FLOW CHARACTERISTICS	
TIME	Bradenhead			Interm		BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg		
5 minutes	0		8			Steady Flow	
10 minutes	0		8			Surges	
15 minutes	0		8			Down to Nothing	
20 minutes	0		8			Nothing	
25 minutes						Gas	
30 minutes						Gas & Water	
						Water	


If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE _____

REMARKS:

No pressure on bradenhead



By Karnie Stufflebeam Witness _____
Switcher
(Position)