NÉW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test	Test <u>F-/1-09</u> Operator			Dugan	Dugan Production Corp.			_API#	30-045-34218					
Property Name	e	CHA	MP	Well No	91S	Location	Unit	D	Section	5.	Township	23N	Rang	e <u>10W</u>
Well Status(Sh	nut-In or Produ	ucing)	, Initial Ps	SI: Tubing	89	Intermed	iate "//	1	Casing	62		Bradenh	ead	O.
														*
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH PRESSURE														
Bradenhead Interm								FLOW	CHARACT	ΓERIS	TICS			
ΤΊΜΕ	BH Int	Csg	Int Cs	<u>g</u>				BRADE	NHEAD	1	INTERMÉ	DIATE .	•	
5 mintues	0	62		_	Steady Flo	w				_				
10 minutes	0	6 Z			Surges						·,			
15 minutes	,o ,	62			Down to No	othing								
20 minutes	0	62			Nothing									
25 minutes					Gas								•	
30 minutes				\neg	Gas & Wat	er							•	
	<u> </u>		·		Water			<u> </u>		<u> </u>		······	•	
							<u></u>	- 0		-			•	
If bradenhead flowed water, check all of the descriptions that apply below:														
	_													
	С	LEAR	<u></u>	FRESH		_SALTY		_SULFU	R	BLAC	K			
5 MINUTE S	SHUT-IN		BRADEN	HEAD	0	_	INTERN	MEDIATE			12348 DIL	(101112 会	2137	1861
									<u> </u>		123	MW 2	009	8192
											V OIL	CONS. DI	V. DIST.	3 27
		•••						<u> </u>	<u> </u>		1.05.65	2 62259		51/1
			_	_								26272	92V	
Ву	for he	<u> </u>	N	<		_	Witness	s						
(Switche	er	· · · · · ·	_								
			(Position)											