

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX (505)334-6170

<http://emnr.state.nm.us/ocd/District/III/3disthc.htm>

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 05-20-09 Operator Dugan Production Corp. API # 30-045-34230
Property Name GOLD MEDAL Well No 94S Location Unit D Section 34 Township 24N Range 10W
Well Status (Shut-In, or Producing) Initial PSI: Tubing 72 Intermediate NA Casing 69 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

TIME	Bradenhead			Interm		
	BH	Int	Csg	Int	Csg	
5 minutes	0		69			
10 minutes	0		69			
15 minutes	0		69			
20 minutes	6		69			
25 minutes						
30 minutes						

Steady Flow

Surges

Down to Nothing

Nothing

Gas

Gas & Water

Water

FLOW CHARACTERISTICS

BRADENHEAD

INTERMEDIATE

Nothing	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____


5 MINUTE SHUT-IN

BRADENHEAD

INTERMEDIATE

REMARKS:

Pressure was zero



By

[Signature]
Switcher
(Position)

Witness