

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

[http://emrnr.state.nm.us/ocd/District III/3distric.htm](http://emrnr.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 5-19-09 Operator Dugan Production Corp. API # 30-045-05618
Property Name WEST BISTI UNIT Well No 156 Location: Unit J Section 36 Township 26N Range 13W
Well Status (Shut-In or Producing) Initial PSI: Tubing 40/185 Intermediate Casing 40/185 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

TIME	Bradenhead			Interm		
	BH	Int	Csg	Int	Csg	
5 minutes	0		40			
10 minutes	0		40			
15 minutes	0		40			
20 minutes	0		40			
25 minutes	0		40			
30 minutes	0		40			

Steady Flow

Surges

Down to Nothing

Nothing

Gas

Gas & Water

Water

FLOW CHARACTERISTICS

BRADENHEAD

INTERMEDIATE

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN

BRADENHEAD

0

INTERMEDIATE

REMARKS:

By Ben Honder 54 Witness _____

Switcher

(Position)

