

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

<http://emnr.state.nm.us/ocd/District/III/3ddistrict.htm>

BRADENHEAD TEST REPORT
(Submit 1 copy to above address)

Date of Test 5-21-09 Operator Dugan Production Corp. API # 30-045-05750
Property Name WEST BISTI UNIT Well No 114 Location: Unit L Section 20 Township 26N Range 13W
Well Status (Shut-In or Producing) Initial PSI: Tubing 11 Intermediate N/A Casing 110 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

TIME	Bradenhead		Interm	
	BH	Int	Csg	Csg
5 minutes	0		110	
10 minutes	0		110	
15 minutes	0		110	
20 minutes	0		110	
25 minutes	0		110	
30 minutes	0		110	

FLOW CHARACTERISTICS

Steady Flow

Surges

Down to Nothing

Nothing

Gas

Gas & Water

Water

BRADENHEAD

INTERMEDIATE

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN

BRADENHEAD 0

INTERMEDIATE _____

REMARKS:

By

Travis Brewton #38

Switcher
(Position)

Witness _____

