

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

<http://emnr.state.nm.us/ocd/District/III/3distnc.htm>

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 20 May 09 Operator Dugan Production Corp. API # 30-045-05914
Property Name HANSON FEDERAL Well No 1 Location: Unit M Section 11 Township 26N Range 11W
Well Status(Shut-In or Producing) Initial PSI: Tubing 240 Intermediate Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

FLOW CHARACTERISTICS

TIME	Bradenhead			Interm				FLOW CHARACTERISTICS	
	BH	Int	Csg	Int	Csg			BRADENHEAD	INTERMEDIATE
5 minutes	0		0				Steady Flow		
10 minutes	0		0				Surges		
15 minutes	0		0				Down to Nothing		
20 minutes	0		0				Nothing	✓	
25 minutes							Gas		
30 minutes							Gas & Water		
							Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE

REMARKS:

By [Signature] Switcher
(Position)

Witness

RECEIVED
JUN 2009
OIL CONS. DIV. DIST. 3