

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

<http://emnr.state.nm.us/ocd/District/III/3distnc.htm>

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 5-20-09 Operator Dugan Production Corp. API # 30-045-23805
Property Name DM NAV 13 26 13 Well No 3 Location: Unit E Section 13 Township 26N Range 13W
Well Status(Shut-In or Producing) Producing Initial PSI: Tubing 8 Intermediate Casing 11 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH


TIME	PRESSURE					FLOW CHARACTERISTICS	
	Bradenhead		Interm			BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg		
5 minutes	0		11			Steady Flow	
10 minutes	0		11			Surges	
15 minutes	6		11			Down to Nothing	
20 minutes						Nothing	✓
25 minutes						Gas	
30 minutes						Gas & Water	
						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE

REMARKS

By  Witness
Switcher
(Position)

