

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 05/19/09 Operator Dugan Production Corp. API # 30-045-26890
Property Name CHAMP Well No 3 Location. Unit A Section 5 Township 23N Range 10W
Well Status(Shut-In or Producing) Initial PSI: Tubing 74 Intermediate Casing 73 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

TIME	Bradenhead			Interm		
	BH	Int	Csg	Int	Csg	
5 minutes	0		73			
10 minutes	0		73			
15 minutes	0		73			
20 minutes						
25 minutes						
30 minutes						

Steady Flow

Surges

Down to Nothing

Nothing

Gas

Gas & Water

Water

FLOW CHARACTERISTICS

BRADENHEAD INTERMEDIATE

BRADENHEAD	INTERMEDIATE

Nothing

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN

BRADENHEAD 0

INTERMEDIATE

REMARKS.

By David S. Williams
Switcher
(Position)

Witness _____

