

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division  
Aztec District Office  
1000 Rio Brazos Road  
Aztec, NM 87410  
(505)334-6178 FAX:(505)334-6170

[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

**BRADENHEAD TEST REPORT**

(Submit 1 copy to above address)

Date of Test 05/19/09 Operator Dugan Production Corp. API # 30-045-26892  
Property Name CHAMP Well No. 2 Location: Unit E Section 5 Township 23N Range 10W  
Well Status(Shut-In or Producing) Initial PSI: Tubing 72 Intermediate ~ Casing 69 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

TIME	Bradenhead			Interm		
	BH	Int	Csg	Int	Csg	
5 minutes	0		69			
10 minutes	0		69			
15 minutes	0		69			
20 minutes						
25 minutes						
30 minutes						

FLOW CHARACTERISTICS

Steady Flow  
Surges  
Down to Nothing  
Nothing  
Gas  
Gas & Water  
Water


BRADENHEAD	INTERMEDIATE
<u>Nothing</u>	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE \_\_\_\_\_

REMARKS:



By David S. Williams  
Switcher  
(Position)

Witness \_\_\_\_\_