NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

Oil Conservation Division

Aztec District Office

1000 Rio Brazos Road

Aztec, NM 87410

(505)334-6178 FAX:(505)334-6170

http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

D-1	Dugan Bradust	ion Corn	A D1 #	20.045	29502			
Date of Test <u>05-18-09</u> Operator						0514	_	40)44
Property Name RED MAC								12W
Well Status(Shut-In or Producing) Initial PSI:	Tubing 2	Intermediate		_Casing _		Bradenh	ead	<u>Ø.</u>
								
OPEN BRADÈNHEAD AND INTERM	EDIATE TO ATM	OSDUEDE IND	ואוסנואו		15 MINILITES	SEVON		
PRESSURE	LDIATE TO ATM	OOFFIERE IND	IVIDUAL	LIFOR	13 MINO I EX	LACIT		
Bradenhea'd Interm			FLOW	CHARACT	TERISTICS			
TIME BH Int Csg Int Csg		•	BRADI	ENHEAD	INTERM	EDIATE		
5 mintues 2	Steady FI	ow						
10 minutes θ 2	Surges				,		•	
21 3	i -						•	
15 minutes	Down to N		11'					
20 minutes	Nothing	No	thing	ļ <u> </u>				
25 minutes	Gas						-	
30 minutes	Gas & Wa	ater						
	Water							
If bradenhead flowed water, che	eck all of the d	escriptions th	at appl	y below	<u>/:</u>			
CLEAR	FDECLI	CALTY	0141.51	ın	DI ACK			
CLEAR	FRESH	SALIY	SULFU)K	BLACK	RECE	10-	
5 MINUTE SHUT-IN BRADENHI	EAD Ø	INTE	RMEDIAT	E	/.	1891011	12132	274
REMARKS:						' E	G.	
					\mathrew{\cdots}	MECE	:IVEI	9 8
			-		Que 1	MULT	5003	920
					180	VIL CUNS. [īv. dist	3 1
		77				6520-	- .1	EN S
					`\	65 ² 82<39	262.46	/
By Jesus M. Lech	1401	14.50						
By Jesus M. Lech.								
Switche	-	Witn	ess				-	