

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

http://emnrd.state.nm.us/ocd/District_III/3district.htm

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 5/20/09 Operator Dugan Production Corp. API # 30-045-29455
Property Name BENGAL C Well No 90 Location: Unit H Section 36 Township 27N Range 13W
Well Status(Shut-In or Producing) Initial PSI: Tubing 10 Intermediate Casing 6 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

FLOW CHARACTERISTICS

TIME	Bradenhead			Interm				FLOW CHARACTERISTICS	
	BH	Int	Csg	Int	Csg			BRADENHEAD	INTERMEDIATE
5 minutes	0		6				Steady Flow		
10 minutes	0		6				Surges		
15 minutes	0		6				Down to Nothing		
20 minutes							Nothing	✓	
25 minutes							Gas		
30 minutes							Gas & Water		
							Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK


5 MINUTE SHUT-IN

BRADENHEAD

0

INTERMEDIATE

REMARKS:



By

[Signature]
Switcher
(Position)

Witness