NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test	Test 5-27,9 Operator				Dugan Production Corp.				3-045-2	063/	1			
	•													0) 47
Property Name ELWOOD P DOWD COM					Location: Unit		<u>N</u>			Township		-	900	
Well Status(Shut-In or Producing) Initial PSI:			Tubing 4		_Intermedia	ediate		_Casing _	6		Bradenl	nead /	0.	
, (,)														<u> </u>
્રે ું OPEN BRAI	DENHEAD		NTERME	DIATE T		SDHERE	ארטואו	וואוום	I V EOR	15 M	IINII ITES E	= V C H		
COP LIN DIVAL		RESSUR		.DIATE I	O ATIVIC	SFIILINE	ואטועו	DUALI	LIIOK	13 IVI	IIINOTESE	_ACI1		
	Bradenhead Interm							FLOW CHARACTERISTICS						
TIME	BH Int						BRADENHEAD			INTERMEDIATE				
5 mintues	0	6] s	teady Flov	- v							-	
10 minutes	D	7	-	1	urges	_							-	
		,		1	-	_							-	
15 minutes	 	6			own to No	thing _			,				-	
20 minutes					lothing	-							-	
25 minutes)	Bas	_							_	
30 minutes		_]	Sas & Wate	er _					++		_	
	•		•	V	Vater	- <u>-</u>						-	_	
If bradenhead flowed water, check all of the descriptions that apply below:														
	C	LEAR		FRESH _		_SALTY _		SULFU	R	BLACI	K	•	•	
5 MINUTE S	SHUT-ÍN	BF	RADENHE	AD _	()		NTERM	IEDIATE	<u> </u>		A BE	71127	31475	
REMARKS:						_					6	公		67
											A BE	<u>CEI</u>	/ED	13
		,									12	ain 21	108	920
				••							// OILC	ONS. DIV	DIST. 3	27/2
·				•							A. O. C.		- مارو	
	-	e Dar	\					·	·			CLZ92	37	
Ву	Witne													
Switcher													_	
(Position)														