

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

<http://emnr.state.nm.us/ocd/District/III/3district.htm>

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 05-18-09 Operator Dugan Production Corp. API # 30-045-29835
Property Name RACHEL Well No 91 Location: Unit K Section 34 Township 26N Range 12W
Well Status (Shut-In or Producing) Initial PSI: Tubing Ø Intermediate T Casing Ø Bradenhead Ø
Well Not producing (well dead)

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

TIME	Bradenhead			Interm		
	BH	Int	Csg	Int	Csg	
5 minutes						
10 minutes						
15 minutes	Ø		Ø			
20 minutes						
25 minutes						
30 minutes						

Steady Flow
Surges
Down to Nothing
Nothing
Gas
Gas & Water
Water

FLOW CHARACTERISTICS

BRADENHEAD	INTERMEDIATE
<u>Nothing</u>	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____


5 MINUTE SHUT-IN

BRADENHEAD

Ø

INTERMEDIATE

REMARKS:



By

Jesus M. Leduaga #26

Witness

Switcher

(Position)