

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division  
Aztec District Office  
1000 Rio Brazos Road  
Aztec, NM 87410  
(505)334-6178 FAX:(505)334-6170

<http://emnr.state.nm.us/ocd/District/III/3district.htm>

**BRADENHEAD TEST REPORT**

(Submit 1 copy to above address)

Date of Test 05-18-09 Operator Dugan Production Corp. API # 30-045-30589  
Property Name SAN JUAN R FEDERAL COM Well No. 90 Location: Unit G Section 12 Township 26N Range 12W  
Well Status(Shut-In or Producing) Initial PSI: Tubing 10 Intermediate - Casing 10 Bradenhead Ø

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

TIME	Bradenhead			Interm		
	BH	Int	Csg	Int	Csg	
5 minutes	Ø		10			
10 minutes	Ø		10			
15 minutes	Ø		10			
20 minutes	Ø		10			
25 minutes						
30 minutes						

Steady Flow  
Surges  
Down to Nothing  
Nothing  
Gas  
Gas & Water  
Water

FLOW CHARACTERISTICS

BRADENHEAD	INTERMEDIATE
Nothing	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN BRADENHEAD Ø INTERMEDIATE \_\_\_\_\_

REMARKS:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

By Jessy M. Lechuaga #96  
\_\_\_\_\_  
Switcher  
(Position)

Witness \_\_\_\_\_

