## NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

http://emnrd.state.nm.us/ocd/District III/3distric.htm

## **BRADENHEAD TEST REPORT**

(Submit 1 copy to above address)

Date of Test <u>5-19-09</u> Operator		Dugan Production Corp.		API #	30-045-32989					
Property Nam	e PATRIOT	Well No94	Location: Unit	A_	Section	29	Township	26N	Range	<u>13V</u>
Well Status(S	hut-In or Producing) Initial PSI:	Tubing <u>100</u>	Intermediate	NA	_Casing	<u>8</u>		Bradenh	ead	0
TIME 5 mintues 10 minutes 15 minutes 20 minutes 25 minutes 30 minutes	ADENHEAD AND INTERMINATE PRESSURE  Bradenhead Interm  BH Int Csg Int Csg  O 6 0  O 7 6 0  O 7 6 0  O 7 6 0  O 7 6 0  O 7 6 0  O 7 6 0  O 7 6 0  O 7 7 7 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8	Steady Flor Surges Down to Nothing Gas Gas & Water	w	FLOW	LY FOR CHARACTENHEAD	TERIST				
<u>lf braden</u>	nead flowed water, che	ck all of the de	scriptions t	hat appl	y belo <u>w</u>	<u>/:</u>				
5 MINUTE REMARKS:	CLEARSHUT-IN BRADENHE	FRESH	_SALTY							
Ву	Travis Brandon Switcher (Position)	**38	Witn	ess	7	12.3.7.00 Oll Oct. 12.3.7.5.00	RECEI JAN 20 CONS. DIV. L	VED OST. 3	1819203	