

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division

Aztec District Office

1000 Rio Brazos Road

Aztec, NM 87410

(505)334-6178 FAX:(505)334-6170

[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 5-19-09 Operator Dugan Production Corp. API # 30-045-33067
Property Name BONANZA Well No 90 Location Unit D Section 26 Township 23N Range 11W
Well Status(Shut-In or Producing) Initial PSI: Tubing 43 Intermediate Casing 68 Bradenhead 1

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

FLOW CHARACTERISTICS

TIME	Bradenhead Interm						BRADENHEAD INTERMEDIATE	
	BH	Int	Csg	Int	Csg			
5 minutes	<u>0</u>		<u>68</u>			Steady Flow		
10 minutes	<u>0</u>		<u>68</u>			Surges		
15 minutes	<u>0</u>		<u>68</u>			Down to Nothing	<u>Down to nothing</u>	
20 minutes	<u>0</u>		<u>68</u>			Nothing		
25 minutes	<u>0</u>		<u>68</u>			Gas		
30 minutes	<u>0</u>		<u>68</u>			Gas & Water		
						Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE

REMARKS:

By Archie Lucera

Switcher
(Position)

Witness _____

