



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3distric.htm](http://emnr.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT


(submit 1 copy to above address)

Date of Test 6-24-09 Operator Canoco API #30-045-20819
Property Name Grumbling A Well No. 4 Location: Unit 1 Section 22 Township 28 Range 8
Well Status (Shut-In or Producing) Initial PSI: Tubing NA Intermediate NA Casing 127 Bradenhead 31

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead	INTERM			
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>127</u>		
10 min	<u>0</u>		<u>127</u>		
15 min	<u>0</u>		<u>127</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow <u>trickle</u>	
Surges	
Down to Nothing	
Nothing	
Gas	
Gas & Water	
Water <u>clear</u> ✓	



If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ✓ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 31 INTERMEDIATE _____

REMARKS:

BH 1" valve with line to holding tank.
No tubing on this well. Steady trickle of water to
tank from BH line. Sample taken

By [Signature]
(Position)

Witness [Signature]

E-mail address _____