NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 5-25-09 Operator			r <u>Duga</u> n	Dugan Production Corp.			1# 30-045-331087					
Property Nam	e HAF	RISON	Well No_	1	_Location: Unit		Section	24	Township	22N	Range	09W
Well Status(SI	hut-In or Produc	ng) Initial F	PSI: Tubing_	Ø.	Intermediate		Casing	0		_Bradenl	nead 🕢	-
												
ODEN DOA		ND ÎNTE			SPHERE IND	ואורואו		15 14	INILITEO	FACU		
OPEN BRA		SSURE	NIEDIATE I	O ATIVIC	SPHERE IND	IVIDUAL	LTFOR	NI GT	INUTES	EACH		
				FLOW CHARACTERISTICS								
TIME	BH Int Cs	g Int C	sg			BRADE	NHEAD		INTERME	DIATE	<u>.</u>	
5 mintues	0			Steady Flov	v							
10 minutes	0 0			Surges					,		_	
15 minutes	6 0			Down to No	thing t						-	
20 minutes				Nothing						,	-	
25 minutes				Gas					·- <u>-</u>		-	
30 minútës	**			Gas & Wate		•					-	
oo minutes	<u> </u>	- II - -		Vater		1 &				*** 1	•	
			·						, .		-	
if bradeni	head flowed	l water, c	heck all of	the des	scriptions th	at apply	y belov	<u>v:</u>		21011	1272	
									3031-1234	9,13	A	37
	CLE	AR	FRESH _		_SALTY	_SULFU	R	BLACK	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	RECE	IVEC	0.7
5 MINUTE SHUT-IN BRADENHE			NHEAD	8	_ INTE	RMEDIATE	Ξ		123	JUN	2008	819
REMARKS:			_	., .	_				1 1 01	L CONS. D	IV. DIST :	202 202
			* ***						150c	**		
1									\96	85728	29276	
	. ,	-										
											-	
		_									-	
Ву	Mikel	ondo			_ Witne	ss		·			_	
		Switch	ner		_							
		(Position)		=							