



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6-30-09 Operator Cenoco API #30-0 45-05726

Property Name Bud-Dos-Pah Well No. 1 Location: Unit Section 19 Township 26 Range 8

Well Status (Shut-In or Producing) Initial PSI: Tubing 27 Intermediate Casing 34 Bradenhead 6
& cemented in

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead Int	Csg	INTERM Int	Csg
TIME					
5 min	<u>0</u>		<u>24</u>		
10 min					
15 min					
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow <u>small trickle</u>	
Surges	
Down to Nothing	
Nothing	
Gas	
Gas & Water	
Water <u>clear</u>	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ✓ FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 6.4 INTERMEDIATE

REMARKS:

BH 1" valve with small steady trickle, sample taken.

Intermed. cemented in

By D.R. Bowman
MSO
(Position)

Witness Richard Bowman



E-mail address