Subi	nit	bν	Email	

Print Form

NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION

AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505 334-6178 FAX (505) 334-6170
http://www.emnrd.state.nm.us/ocd/

BRADENHEAD TEST

	.,	······································							
Date of Test 05	5/21/2009		Operator	Breck Operatin	g		API#	30-045-07341	
Property Name	<u> </u>	rnment #9	Loca	tion: Unit E	Section	20 Township 28	BN Ran	ge 10W	
Well Status: Sh	ut-in or Pr	oducing [Producing						
Pressures:	Tubing [1		termediate n	a Casing	24	Bradenhead 0	· · · · · · · · · · · · · · · · · · ·		
OPEN	BRADENH	EAD AND	INTERMEDIA	ATE TO ATMOSI	PHERE INC	DIVIDUALLY FOI	R 15 MII	NUTES EACH	
Bradenhead PSIs			PSIs	Intermediate			Bradenhead Intermediate		
<u>Time</u>	BH Blowdown	Casing Monitor	INT Monitor	Intermediate Blowdown	Casing Monitor		ыас	genneau intermediate	
30 minutes	0 0 0	24 24 24 24 24 24	NA NA NA	NA [NA [NA] NA [NA]		Steady Flo Surge Down to Nothin No Flo G Gas and Wat	es		
<u>lf bradenhea</u>	ad flowed v	water, che	ck all of the	descriptions tha	it apply be	<u>low:</u>		62128293037	
Clear 🔲	F	resh 🔲	Sa	alty 🔲	Sulfur	В	lack (BECTIVE S	
5 Minute Sh	i ut-in E	Bradenhead	0	Intermediate	na			SECONO DIL CONS DIL DIL SECONO DIL CONS	
REMARKS:	·			92 - 1 (0 - 101 - 1119 - 1112 - 1111 - 1111 - 1111				RECEIVED STORY OIL CONS. DIV. DIST. 3	
By: Harley Cher	ttınger					Witness:			
	(Posit	tion)	•						