-	C I	**		<b>Email</b>
	NIID	mit	nv	-m20
	JUU	11111	· D V	LIIIG
		- 7		

Print Form

## NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION

AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505 334-6178 FAX (505) 334-6170
http://www.emnrd.state.nm.us/ocd/

## **BRADENHEAD TEST**

<u></u>			<b></b>						
Date of Test 09	5/21/2009		Operator	Breck Operating	3		API#	30-045-31632	
Property Name	L	nment #85 e and Numbe	Location	on: Unit C	Section 21	Township 2	8N Rang	ge 10W	
Well Status: Sh	nut-in or Pro	ducing Pr	roducing						
ressures:	Tubing 3	Inte	ermediate na	Casing	20 Br	adenhead 0	wikida da matida marangan		
OPEN	BRADENHE	AD AND I	NTERMEDIAT	E TO ATMOSP	HERE INDIV	IDUALLY FO	R 15 MII	NUTES EACH	
Bradenhead PSIs			SIs	Intermediate			Bradenhead Intermediate		
<u>Time</u>	BH Blowdown	Casing Monitor	INT Monitor	Intermediate Blowdown	Casing Monitor		Didu	ienneau intermediate	
5 minutes 10 minutes 15 minutes 20 minutes 25 minutes 30 minutes	0	20 [	NA NA NA NA	NA [ NA [ NA [ NA ] NA [ NA ] NA [ NA ]		Steady Flo Surg Down to Nothi No Fl G Gas and Wa	ges		
If bradenhe		vater, chec	k all of the de	escriptions that	"		3lack [	15062128293037	
5 Minute Sh		radenhead	0	Intermediate	na	]		RECEIVED SON OIL CONS. DIV. DIST	
INLIWARTS.	· · · · · · · · · · · · · · · · · · ·	***************************************	yn (* 111 - 11 - 11 - 11 - 11 - 11 - 11 -	digi ya garan da kana da kana ka a ka a ka a ka a k	n y ar mangangan akin an	***************************************		OIL CONS. DIV. DIST : 30	
By: Harley Che	ttinger				V	Vitness:			
	(Positi	on)							