	42 AMS -	ANN	4.4
Subr	~ i+"l	4:77 E.s	nail
Subi	11113	JV∘⊑i	IIdli 🔻

Print Form

## NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION

AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC, NM 87410 (505 334-6178 FAX. (505) 334-6170 http://www.emnrd.state.nm.us/ocd/

RCVD JUL 7'09

OIL CONS. DIV.

DIST. 3

		$\overline{}$	umpson En	·G F	erad: e				
Date of Test 0	5/14/09	Operator (	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		יו# <sub>30-045-23803</sub>	3			
Property Name	Southland #6 (Well Name and Number)		nit H Section	10 Township 26N	Range 13W				
Well Status: Shut-in or Producing Shut-in									
ressures:	Tubing 0 Inte	rmediate na C	asıng 0	Bradenhead 0					
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH									
Bradenhead PSIs Intermediate					Bradenhead Intermediate				
<u>Time</u>	BH Casing Blowdown Monitor	INT Interm Monitor Blow		·		- Tillouiato			
5 minutes 10 minutes 15 minutes 20 minutes 25 minutes 30 minutes		a na na		Steady Flow Surges Down to Nothing No Flow Gas Gas and Water Water					
If bradenhead flowed water, check all of the descriptions that apply below:									
Clear 🔲	Fresh 🗖	Salty [	Sulfur	☐ Black					
5 Minute Sh	ut-in Bradenhead	0 Intermed	diate na						
REMARKS:	naver i i i i i i i i i i i i i i i i i i i	10-10-10-10-10-10-10-10-10-10-10-10-10-1		uunuummaanna valtaanii ka	····				
ta mentero control de la contr									
By: Kenny Bruc	e operator		***************************************	Witness:					

(Position)

**BRADENHEAD TEST**