Subm	it bv	Email	

Print Form

NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION

AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC, NM 87410 (505 334-6178 FAX. (505) 334-6170 http://www.emnrd.state.nm.us/ocd/

BRADENHEAD TEST

Date of Test	05/25/09	Operator Running Ho	rse Production	API # 30	0-045-28368
	Nassau Texaco 12 #12 (Well Name and Number) hut-in or Producing pro Tubing 14 Interi	Location: Unit		immed and a second a second and	12w JUL 7'09 CONS. DIV.
	BRADENHEAD AND INT Bradenhead PSI BH Casing	ls Interd	mediate		TES EACH
5 minutes 10 minutes 15 minutes 20 minutes 25 minutes 30 minutes		Monitor Blowdow	Si Down	teady Flow Surges to Nothing No Flow Gas and Water Water	
If bradenhe	ad flowed water, check a	Salty	hat apply below: Sulfur	Black ☐	
5 Minute Sh REMARKS: By: Kenny Bruc		Intermediate		:	