c 1		E 41
Subm	nt by	/ Email

Print Form

NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION

AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505 334-6178 FAX (505) 334-6170
http://www.emnrd.state.nm.us/ocd/

BRADENHEAD TEST

Date of Test	06/04/2009		Operator	Coleman Oil &	Gas	/	API# 30-045	-30297		
Property Nam			Location	on: Unit D	Section	n 26 Township 26N	Range 12W			
Well Status: S				Casing	5	Bradenhead 0				
ressures: OPEN						DIVIDUALLY FOR	15 MINUTES	EACH		
	Bra	denhead P	Sis	Interme	diate					
<u>Time</u>	BH Blowdown	Casing Monitor	INT Monitor	Intermediate Blowdown	Casing Monitor		Bradenhead	I Intermediate		
5 minutes 10 minutes 15 minutes 20 minutes 25 minutes 30 minutes	0	5		NA [NA] NA [NA] NA [NA]		Steady Flow Surges Down to Nothing No Flow Gas Gas and Water Water				
If bradenhead flowed water, check all of the descriptions that apply below: Clear Fresh Salty Sulfur Black 5 Minute Shut-in Bradenhead Intermediate Na REMARKS:										
Clear _		resh 🔲	Salty 0	_	Sulfur	☐ Blad	CK SE SUL CONS	CEIVED 2314156 S. DIV. DIST. 3		
REMARKS:							75.52 S.	52120 <u>20</u> 202122		
By: Michael Ve		20)				Witness:				
	(Position	(110								