Sub	mit	bý	Email

Print Form

## NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION

AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505 334-6178 FAX (505) 334-6170
http://www.emnrd.state.nm.us/ocd/

## **BRADENHEAD TEST**

Date of Test 6-	18-09	Operator	Coleman Oıl & G	as	API#	30-045-31734		
Property Name MARILYN COM #0015 Location: Unit O Section 24 Township 26N Range 12W  (Well Name and Number)  Well Status: Shut-in or Producing Producing								
Pressures: Tubing 35 Intermediate Casing 13 Bradenhead 0								
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH								
Bradenhead PSIs		PSIs	Intermediate		Brac	denhead Intermediate		
10 minutes 15 minutes 20 minutes 25 minutes 30 minutes	BH Casing Monitor  0 13  0 13  0 13  0 0 10	INT Monitor		Down to N No Gas and	Surges Othing Othing So Flow So Gas			
If bradenhead flowed water, check all of the descriptions that apply below:  Clear								
5 Minute Sh			Intermediate		93037	RECEIVED SA		
By: Mike Veaze	y, Lease opperator (Position)			Witness:	397	CONS. DIV. DIST. 3		