



NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
[http://emnr.state.nm.us/ocd/District III/3distric.htm](http://emnr.state.nm.us/ocd/District%20III/3distric.htm)

**BRADENHEAD TEST REPORT**

(submit 1 copy to above address)

Date of Test 5-13-09 Operator Lizard Production API #30-0 45-25440  
Property Name Hatch Well No. 1 Location: Unit    Section 11 Township 29N Range 15W  
Well Status (Shut-In or Producing) Initial PSI: Tubing 0 Intermediate N/A Casing 25 Bradenhead 1

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

| Testing | PRESSURE   |            |            |            |            |
|---------|------------|------------|------------|------------|------------|
|         | Bradenhead |            |            | INTERM     |            |
|         | BH         | Int        | Csg        | Int        | Csg        |
| TIME    |            |            |            |            |            |
| 5 min   | <u>3</u>   | <u>N/A</u> | <u>120</u> | <u>N/A</u> | <u>N/A</u> |
| 10 min  | <u>0</u>   | <u>N/A</u> | <u>50</u>  | <u>N/A</u> | <u>N/A</u> |
| 15 min  | <u>0</u>   | <u>N/A</u> | <u>25</u>  | <u>N/A</u> | <u>N/A</u> |
| 20 min  | <u>0</u>   | <u>N/A</u> | <u>25</u>  | <u>N/A</u> | <u>N/A</u> |
| 25 min  | <u>0</u>   | <u>N/A</u> | <u>25</u>  | <u>N/A</u> | <u>N/A</u> |
| 30 min  | <u>0</u>   | <u>N/A</u> | <u>25</u>  | <u>N/A</u> | <u>N/A</u> |

|                 | FLOW CHARACTERISTICS |              |
|-----------------|----------------------|--------------|
|                 | BRADENHEAD           | INTERMEDIATE |
| Steady Flow     | <u>  </u>            | <u>N/A</u>   |
| Surges          | <u>  </u>            | <u>N/A</u>   |
| Down to Nothing | <u>X</u>             | <u>  </u>    |
| Nothing         | <u>  </u>            | <u>  </u>    |
| Gas             | <u>  </u>            | <u>  </u>    |
| Gas & Water     | <u>  </u>            | <u>  </u>    |
| Water           | <u>  </u>            | <u>  </u>    |

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR    FRESH    SALTY    SULFUR    BLACK   

RCVD MAY 22 '09  
OIL CONS. DIV.  
DIST. 3

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 3

INTERMEDIATE N/A

REMARKS:

Treat well for Paraffin before test 3 Days shut-in.  
Well on - Left Bradenhead valve open to Pipe above ground

By Adh Sullivan  
Pumper  
(Position)

Witness   

E-mail address lizard35@wildblue.net