NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

http://emnrd.state.nm.us/ocd/District.III/3distric.htm

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

	د. سي				_	.		•			00.045	0700				
Date of Test <u>5-/2-09</u> Operator																
Property NameTURKS TOAST										_			_			
Well Status(Sh	ut-In of Pró	ducing)) Initia	I PSI:	Tubing	215.6	<i>PSI</i> 1	ntermed	iate		_Casing	215	PSI	Bradenl	nead ´	25 BZ
<u></u>													*			
	DENILEA	D A N I I) INITE	- D N 4 É	ירועדר -		100	חווכסו	÷ 181018	//	LV	4 E NAI	INILITEO	E A O L L		
OPEN BRA				- KIVIE	DIATE	IOAIN	105	PHEKI	יוטאו ב	IDUAL	LYFUR	15 IVII	INUTES	EACH		
	PRESSURE Bradenhead Interm									FLOW	CHARACT	TERIŠT	ics	4		
TIME	BH Int			Csg							ENHEAD		INTERME	DIATE		
5 mintues	0	215	II I]	Steady Fl	low		•						-	
10 minutes	0	2/5			1	Surges						-			-	
	0	215			1		h								_	
15 minutes		100			1	Down-to-1	Nothi	ng >		·						
20 minutes	 	1	5		1	Nothing									-	
25 minutes		<u> </u>				Gas				_					-	
30 minutes						Gas & Wa	ater								_	Ŷ
						Water									_	
If bradenhead flowed water, check all of the descriptions that apply below:																
		CLEAR						CALTY		CUI FU	ID	DI A CI	,			
		CLEAR	·		_ FRESH .		—`	SALIT		_SULFU	JR	BLACK		_		
5 MINUTE	SHUT-IN		BRAD	ENHEA	AD	0			INTER	MEDIATE	=			011121	31415	70
REMARKS:					•					-			\ose \(^2\)		<u>.</u>	المين المناف
													6	RFCE	IVE	
ź													346	اللا	200B	16118 1920212
										-			\c\ \c\ \c\	OIL CONS	DIV. DIS	T.3 N
•			•										4	<u>. </u>	-	3202122 31. 33. 75. 32. 75. 32. 75. 32. 75. 32. 75. 32. 75. 32. 75. 32. 75. 75. 75. 75. 75. 75. 75. 75. 75. 75
-				_										OE 6787	1797	30.
Ву	10	ho		25	? 	<i></i>			Witnes	c						
Jy	11 0		Swite		-/				A A I II 10.2						-	
			(Positi		<u> </u>											