

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

<http://emnrds.state.nm.us/ocd/DistrictIII/3district.htm>

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 5-12-09 Operator Dugan Production Corp. API # 30-045-30719
Property Name TURKS TOAST Well No 93 Location: Unit G Section 19 Township 30N Range 14W
Well Status(Shut-In or Producing) Initial PSI: Tubing 0 PSI Intermediate Casing 7 PSI Bradenhead 0 PSI

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

TIME	Bradenhead			Interm		
	BH	Int	Csg	Int	Csg	
5 minutes	0		7			
10 minutes	0		7			
15 minutes	0		7			
20 minutes						
25 minutes						
30 minutes						

Steady Flow

Surges

Down to Nothing

Nothing

Gas

Gas & Water

Water

FLOW CHARACTERISTICS

BRADENHEAD

INTERMEDIATE

	RCVD JUL 13 '09
	OIL CONS. DIV.
	DIST. 3

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN


BRADENHEAD

0

INTERMEDIATE

REMARKS:

By


Switcher
(Position)

Witness