NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

Öil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX.(505)334

http://emnrd state.nm.us/ocd/District III/3distric.ht

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 3,-26:69 Operator	Dugan Production Corp.	API# 30-045-33186
Property Name BITSILI	Well No 1 Location: Unit	G Section 19 Township 24N Range
Well Status(Shut-In or Producing) Initial PSI:	Tubing 65 Intermediate	Casing <u>65</u> Bradenhead <u></u>
OPEN BRADENHEAD AND INTERM	EDIATE TO ATMOSPHERE IND	IVIDUALLY FOR 15 MINUTES EACH
PRESSURE		
<u> </u> Bradenhead Interm		FLOW CHARACTERISTICS
TIME BH Int Csg Int Csg	_	BRADENHEAD INTERMEDIATE
5 mintues 0 . 65	Steady Flow	·
10 minutes	Surges	
15 minutes	Down to Nothing	
20 minutes	Nothinġ	
25 minutes	Gas	
30 minutes	Gas & Water	
·	Water	
If bradenhead flowed water, che	eck all of the descriptions th	nat apply below:
CLEAR	FRESHSALTY	SULFURBLACK
5 MINUTE SHUT-IN BRADENHI	EAD INTE	RMEDIATE BLACK RECEIVED RECEIVED
RÈMARKS:		
		/2º RECEIVED 3
		23 JUL 2009
		VI ONS. DIV. DIST 3
		2585728282 Aprel 10 12 13 12 13 12 13 12 13 12 13 12 13 13 13 13 13 13 13 13 13 13 13 13 13
	1	\$6.25282728gs
By	Witne	ess
S witcher		
(Position)		