## NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

http://emnrd.state.nm.us/ocd/District III/3distric.htm

## **BRADENHEAD TEST REPORT**

(Submit 1 copy to above address)

Date of Test 5-21-9 Operator			Dugan Production Corp.				_API#	30-045-26926				_	
Property Name	MONTI	REAL	Well No_	2	Location:	Unit	E_	Section	4_	Township	23N	Range	e <u>10\</u>
Well Status(Shut-In or Producing) Initial PSI:			Tubing_	45	Intermedia	ate .		_Casing _		5	Bradeni	n <u>ead</u>	0
TIME 5 mintues 10 minutes 15 minutes 20 minutes 25 minutes 30 minutes	DENHEAD ANI PRESS Bradenhead BH Int Csg O 55 O 5	Interm Int Csg		Steady Flo Surges Down to N Nothing Gas Gas & Wa Water	ow lothing ter		FLOW	CHARACT	ERIS	TICS	DIATE	- - - -	
	CLEAF	₹	_FRESH _		SALTY		SULFU	IR	BLAC	K	Ta 40.0		
5 MINUTE S REMARKS:	SHUT-IN	BRADENHE	4D _	<i>O</i>		INTER	MEDIATE			\$ REC. 1011 CO. 101 CO	121374 DEIVE DEIZOO NS. DIV. D	PO ISL 3	192021222
Ву	_mtei	Switcher	005.	3	_	Witnes	ss	·····	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,			_	

(Position)