

## NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District III/3distric.htm

## **BRADENHEAD TEST REPORT**

(submit 1 copy to above address)

Date of	f Test	6-	23-	09 or	erator_	may D	. Wb.bb API	#30-0 45-26593
Property Name Jeden 27 Well No. 9 Location: Unit Le Section 27 Township 27 Range 13								
Well Status (Shut-In or Producing) Initial PSI: Tubing O Intermediate Casing 70 Bradenhead C								
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH								
Testing	BH Int Csg Int Csg					FLOW CHARACTERISTICS BRADENHEAD INTERMEDIATE		
TIME 5 min_	D		70			Steady Flow_		
10 min_	D		70			Surges		
15 min_	0		70			Down to Noti	hing	<u>'</u>
20 min_						Nothing	<u></u>	
25 min_						Gas		
30 min_						Gas & Water		23242526273
						Water		7727 A BE
If bradenhead flowed water, check all of the descriptions that apply below:								
CLEAR			FRESH SALTY			SULFUR	BLACK	OIL CONS. DIV. DIST. 3
If bradenhead flowed water, check all of the descriptions that apply below:  CLEAR FRESH SALTY SULFUR BLACK  SMINUTE SHUT-IN PRESSURE BRADENHEAD INTERMEDIATE  REMARKS:  Gas & Water  Water  RECEIVED  OIL CONS. DIV. DIST. 3  OIL CONS. DIV. DIST. 3  REMARKS:								
REMARKS: Jump JACK								
By Mar Ciable Witness								
By Mar Ciabl Witness								
E-mail address								