



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emrdr.state.nm.us/ocd/District III/3district.htm](http://emrdr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7-27-09 Operator Conoco API #30-0 45-23638

Property Name Navajo B Well No. 6m Location: Unit Section 19 Township 27 Range 8

Well Status (Shut-In or Producing) Initial PSI: Tubing 168 Intermediate NA Casing 184 Bradenhead 82

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead		INTERM		
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>135m</u>		<u>185</u>		
10 min	<u>0</u>		<u>186</u>		
15 min	<u>0</u>		<u>186</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow <u>☒</u>	
Surges <u> </u>	
Down to Nothing <u> </u>	
Nothing <u> </u>	
Gas <u> </u>	
Gas & Water <u> </u>	
Water <u> </u>	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK ☒

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 14 INTERMEDIATE

REMARKS:

1" hose pipe from BH to BGT, Surges in water flow,
Black color then just gas after 5 min.

By Travis Rowland
MSO-COPC
(Position)

Witness

Rachel Morgan

E-mail address

