submitted in lieu of Form 3160-5

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

RECEIVED

AUG 0 7 2009

OMPANY LP (505) 326-9700		5. 6. 7. 8.	Lease Number SF-080672 If Indian, All. or Tribe Name Unit Agreement Name San Juan 27-4 Unit Well Name & Number SJ 27-4 Unit #109A
		8.	San Juan 27-4 Uni Well Name & Number SJ 27-4 Unit #109A
			Well Name & Number SJ 27-4 Unit #109A
(505) 326-9700			SJ 27-4 Unit #109A
(505) 326-9700		9.	
	PO Box 4289, Farmington, NM 87499 (505) 326-9700		API Well No.
Location of Well, Footage, Sec., T, R, M			30-039-30618
Unit B (NWNE), 1160' FNL & 2485' FEL, Section 23, T27N, R4W, NMPM		10.	Field and Pool
Unit B (NWNE), 1000' FNL & 1400' FEL, Section 23, T27N, R4W, NMPM			Blanco MV / Basin DK
	···	11.	County and State Rio Arriba, NM
DICATE NATU	RE OF NOTICE, REPO	ORT, OTHER	DATA
ı Abandonment	X Change of Plans		Other - Csg design change
-			ROVD AUG 12 'GE
Casing Repair	Water Shut off	_	OIL COVS. DIV.
Altering Casing	Conversion to Inj	ection	
	DICATE NATU Abandonment Recompletion Plugging	DICATE NATURE OF NOTICE, REPORT Abandonment Recompletion Plugging Casing Repair Altering Casing Conversion to Inj	EL, Section 23, T27N, R4W, NMPM EL, Section 23, T27N, R4W, NMPM 11. DICATE NATURE OF NOTICE, REPORT, OTHER Abandonment Recompletion Plugging Non-Routine Fracturing Casing Repair Altering Casing Conversion to Injection