OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/DistrictIII/3distric.htm

## BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test	8-21-09	Operator Western Miner	als & Oil LLC	API #30-0	39-82334	
Property Name	Hurt	Well No. 1	Location: Unit	E Section 1	1Township	25N Range 03W
Well Status (Shu	t-In or Producing)	Tubing 62	Intermediate	Casing	Bradenhead	<u> </u>
(	OPEN BRADENHEAI	AND INTERMEDIATE	TO ATMOSPHERE	INDIVIDUALLY	FOR 15 MINUT	TES EACH
TIME	PRESSURES: INTERMEDIATE	CASING			BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes	-	62	Steady Flow		4,44	
10 minutes		62	Surges			
15 minutes		62	Down to Nothing		X	-
20 minutes		6a	Nothing			
25 minutes		<u> </u>	Gas			141516:
30 minutes		(A)	Gas & Water		(5)121	1010/10/10
			Water	<u></u>	OF PE	CEIVED &
30 minutes  Gas & Water  Water  Water  H bradenhead flowed water, check all of the descriptions that apply below:  CLEAR FRESH SALTY SULFUR BLACK						
CLEAR	FRESH	SALTY	SULFUR	BLACK		1505 62 82 123 13
5 MINUTE SHUT-IN BRADENHEAD INTERMEDIATE						
REMARKS BIG	ew dou	on to no	thing 1	n less	5 Han	2 second
				And the second s		
Ву	Bob Ch	maultwith	iess			
	(Positio	nn)				