OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC , NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/DistrictIII/3distric.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

| Date of Test | 9/2/09 Operator M&G Drilling Company | | | | | API #30-0 | | 45-33835 | |
|--|--------------------------------------|----------|-----|----------------|----|-----------|---|---------------------|------------------------|
| Property Name | KRAUSE 33 | Weil No. | 103 | Location: Unit | Н | Section | 33 | Township | 28N Range 11W |
| Well Status (Shu | t-In or Producing) | Tubing | | Intermediate | NA | _Casing | 9 | _Bradenhead | 0 |
| OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH | | | | | | | | | |
| TIME | PRESSURES: INTERMEDIATE | CASING | | • | | | В | RADENHEAD FLOWED | INTERMEDIATE FLOWED |
| 5 minutes | N/A | 9 | | Steady Flow | | N | 074/ | NG | N/A |
| 10 minutes | | 9 | | Surges | | | | | |
| 15 minutes | | 9 | | Down to Nothin | g | | | | |
| 20 minutes | | | | Nothing | | | | | |
| 25 minutes | | | | Gas | | | $-\!$ | | |
| 30 minutes | | | | Gas & Water | | | 1 | / | |
| | | | | Water | | | | | <u> </u> |
| If bradenhead flowed water, check all of the descriptions that apply below: | | | | | | | | | |
| CLEAR | FRESH | SALTY | | SULFUR | BI | ACK | | (18910 | 4 1576 |
| CLEAR FRESH SALTY SULFUR BLACK \$\frac{1}{2} \frac{1}{2} 1 | | | | | | | | | |
| REMARKS: | | | | | | | | | |
| Estation of the state of the st | | | | | | | | | |
| | | | | | | | | | |
| By Cantal Places Witness | | | | | | | | | |
| 1 Pumper | | | | | | | | | |
| | (Position) | <i>F</i> | | | | | 1 | | |