

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

*Needs well bore
Diagram*

Date of Test 9/3/09 Operator M&G Drilling Company API #30-0 45-22859
Property Name KRAUSE Well No. 65 Location: Unit C Section 33 Township 28N Range 11W
Well Status (Shut-In or Producing) Tubing Ø Intermediate N/A Casing 16 Bradenhead N/A

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD	INTERMEDIATE
	INTERMEDIATE	CASING		FLOWED	FLOWED
5 minutes	<u>N/A</u>	<u>16</u>	Steady Flow	<u>N/A</u>	<u>N/A</u>
10 minutes	<u>L</u>	<u>16</u>	Surges		
15 minutes	<u>✓</u>	<u>16</u>	Down to Nothing		
20 minutes			Nothing		
25 minutes			Gas		
30 minutes			Gas & Water		
			Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD N/A INTERMEDIATE N/A

REMARKS:

NO BRADEN HEAD VALVES. OLD STYLE WELL HEAD. LONG STRING CASING
IS SITTING ON SURFACE WITH WELDED PLATE. NO SEAL
CEMENT TO SURFACE.

By [Signature] Witness _____

(Position)



M&G DRILLING COMPANY, INC.

KRAUSE #65

LEASE NO. NMSF 078863

C SEC. 33: T28N-R11W

SAN JUAN COUNTY, NM

API # 30-045-22859

SPUD: 1/04/78

1ST DELIVERY: 7/11/78

