



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 11-4-09 Operator MEG Mulling Co. API #30-0 45-06386

Property Name Maunon Well No. 38 Location: Unit E Section 23 Township 27 Range 8

Well Status (Shut-In or Producing) Initial PSI: Tubing 51 Intermediate N/A Casing 72 Bradenhead 59

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead		INTERM	
		Int	Csg	Int	Csg
TIME					
5 min			<u>71</u>		
10 min			<u>71</u>		
15 min			<u>71</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow <u>/</u>	
Surges	
Down to Nothing	
Nothing	
Gas	
Gas & Water	<u>RCUD NOV 4 '09</u>
Water <u>/</u>	<u>OIL CONS. DIV.</u>

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR / FRESH _____ SALTY _____ SULFUR _____ BLACK Gray

DIST. 3

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 56

INTERMEDIATE N/A

REMARKS:

Had blow with water when opened - then 1/2"
stream for all of 15 minutes at 5 gallons every
4 minutes water gray when opened to clear test

By Dan Kinson

Witness Monica Cullum

Manager
(Position)

E-mail address _____