



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 11-4-09 Operator M.E. Gullung API #30-0 45-25485
Property Name Graham Well No. 3 Location: Unit 3 Section 3 Township 27 Range 8
Well Status (Shut-In or Producing) Initial PSI: Tubing Chakua 4 Intermediate N/A Casing 66 Bradenhead 42

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min			66		
10 min			66		
15 min			69		
20 min			70		
25 min			71		
30 min			72		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow <u>✓</u>	
Surges	
Down to Nothing	
Nothing	
Gas	RCUD NOV 4 '09
Gas & Water	OIL CONS. DIV.
Water <u>✓</u>	DIST. 3

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ✓ FRESH _____ SALTY _____ SULFUR _____ BLACK ✓

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 34

INTERMEDIATE N/A

REMARKS:

Puff of water then started flowing 1/8" Black to clear
water in 2 minutes - 4 in 12
3 in 21.5
242 in 30 total 9 1/2 in 30 minutes

By Daniel Hinson
Manager
(Position)

Witness Mona Gullung

E-mail address _____