

Bill Richardson

Governor

Joanna Prukop Cabinet Secretary Mark Fesmire
Division Director
Oil Conservation Division



October 16, 2009

Sharon Zubrod ConocoPhillips Company 3401 E 30th Street Farmington, NM 87402

Re: Angel Peak B #30, B-13-28N-11W, API # 30-045-24530

Dear Ms. Zubrod:

The 2009 Bradenhead test on the above well indicates a failure. In order to comply with Rule 19.15.16.11, prevent waste and protect fresh water, you are hereby directed to initiate remedial activity before January 18, 2010. Initial Bradenhead psi of 92 was reported with a "light vent" throughout the test and a 5 minute shut in pressure of 75 psi. The production casing pressure dropped from 92 psi to 74 psi.

With your sundry please attach a copy of the last two tests, a current wellbore schematic including formation and cement tops. Indicate the method used to determine the cement tops, and provide gas analysis from all casing strings.

Reference: RBDMS KGR0928842797 on future correspondence for this well.

Notify the Aztec OCD 24 hours before work is initiated.

If you have any questions, please call me at 505-334-6178, ext. 16.

Sincerely yours,

Kelly Roberts

Deputy Oil and Gas Inspector

District III - Aztec

CC: Well File

