


30045 09259

FARMINGTON OFFICE COPY

Form 9-381a (Feb. 1951)

Budget Bureau No. 42-R358.4 Approval expires 12-31-60.



(SUBMIT IN TRIPLICATE)

Land Office Santa Fe Lease No. 077372 Unit

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

Table with 2 columns: NOTICE OF INTENTION TO DRILL, CHANGE PLANS, TEST WATER SHUT-OFF, RE-DRILL OR REPAIR WELL, SHOOT OR ACIDIZE, PULL OR ALTER CASING, ABANDON WELL; and SUBSEQUENT REPORT OF WATER SHUT-OFF, SHOOTING OR ACIDIZING, ALTERING CASING, RE-DRILLING OR REPAIR, ABANDONMENT, SUPPLEMENTARY WELL HISTORY.

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Dansby

July 12, 19 58

Well No. 1 is located 660 ft. from N line and 1980 ft. from E line of sec. 30

NE 1/4 sec. 30 30 N 12 W N.M.P.M. (Range) (Meridian)

Fulcher-Kutz San Juan New Mexico (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5713 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Placed cement plug from T.D. to 1400 feet. Recovered approximately 800 feet of 5 1/2" casing. Placed 100 foot plug on 5 1/2" stub. Placed 50 foot plug from 450 to 500 feet. Installed regulation marker and cleaned up location.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company C. V. Lyman

Address Box 1111

Midland, Texas

By V. L. Wheeler

Title Agent

Inspected by P. T. McGrath 7-12-58 OK