

30 045 09402

Budget Bureau 42-R358.2.
Approval expires 12-31-52.Form 9-331a
(Feb. 1951)

(SUBMIT IN TRIPPLICATE)

Land Office SANTA FELease No. SF 077372

Unit _____

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

APPROVED SEP 24 1953
ACTING DISTRICT ENGINEER

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	SUBSEQUENT REPORT OF OIL-SAND-FRAC

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

SEPTEMBER 24, 19 53

Well No. 2 DANDY is located 990 ft. from [N] line and 990 ft. from [E] line of sec. 19

NE-NE (1/4 Sec. and Sec. No.) 30N-12W (Twp.) N.M.P.M. (Range) (Meridian)

WILDOAT (Field) SAN JUAN (County or Subdivision) NEW MEXICO (State or Territory)

The elevation of the derrick floor above sea level is 5848 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

8/28/53 RAN OIL-SAND-FRAC JOB. PUMPED 160 BBLs. OF 41° GRAVITY OIL AND 1600 LBS. OF CLEAN QUARTZ SAND INTO PICTURED CLIFFS SS. FROM 1945 TO 1982. FORMATION BROKE DOWN AT 1500 PSI, TOOK OIL CONTINUOUSLY AT 1000 PSI. INJECTION RATE APPROXIMATELY 2 BBLs. OIL PER MINUTE. GAGED 5000 CU. FT. GAS PER DAY BEFORE O-S-F JOB.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company DON TRADERS INC.
254 NO. LAUREL AVE.
Address DES PLAINES, ILL.

By Frank C. Barnes
FRANK C. BARNES

Title GEOLOGIST