

30 045 09402

CorrectedBudget Bureau 42-R358 3.
Approval expires 12-31-55.Form 9-381a
(Feb. 1951)

(SUBMIT IN TRIPLICATE)

Land Office **SANTA FE**
Lease No. **SF-077372**
Unit _____UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

SEPTEMBER 20, 1953

Well No. **2 DANEY** is located **990** ft. from **N** line and **990** ft. from **E** line of sec. **19****NE-NE**

(1/4 Sec. and Sec. No.)

30N-12W

(Twp.) (Range)

N.M.P.M.

(Meridian)

WILDCAT

(Field)

SAN JUAN

(County or Subdivision)

NEW MEXICO

(State or Territory)

The elevation of the derrick floor above sea level is **5848** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

CEMENTED **5-1/2"** CASING AT **1945'** WITH **125** BAGS OF CEMENT. TESTED WITH **500#** PRESSURE BEFORE AND AFTER DRILLING PLUG. NO LEAKS AND NO WATER.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **DON TRADERS INC**Address **254 NO. LAUREL AVE.****DES PLAINES, ILL.**By **F.C. BARNES**Title **GEOLOGIST**