

District I
1625 N French Dr., Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

API # 30-045-05223

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Maralex Resources, Inc.	Contact	D. Jeremy Golob
Address	P.O. Box 338	Telephone No.	970-563-4000
Facility Name	Patty #1	Facility Type	Oil Well

Surface Owner	BLM	Mineral Owner	BLM	Lease No.	NMNM036252A
---------------	-----	---------------	-----	-----------	-------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	27	25N	11W	1980	S	660	E	San Juan

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	Oil Spill	Volume of Release	17bbl	Volume Recovered	16+ bbl
Source of Release	Containment overflow	Date and Hour of Occurrence	Date and Hour of Discovery		
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	9/28/09 11:30 am 9/28/09 12:30p		
By Whom?	D. Jeremy Golob	Date and Hour	C. Perrin, NMOCD		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

Separator malfunctioned causing water to flow into oil containment tank.
Maralex will install high tank level safety device to prevent future occurrence.

Describe Area Affected and Cleanup Action Taken.*

Removed oil from berm and contaminated soil from berm. Surrounding sagebrush stained with oily mud. Sagebrush will be pressure washed per NMOCD recommendations.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION		
Printed Name: Doris K. Ney	Approved by District Supervisor:  For: CP		
Title: Production Technologist	Approval Date: 10-7-09	Expiration Date:	
E-mail Address: dneym@maralexinc.com	Conditions of Approval:	Attached <input type="checkbox"/>	
Date: 09/29/2009	Phone: 970 563 4000		

* Attach Additional Sheets If Necessary

cc: Bill Luss, BLM, Farmington

Incident # NMD 0928054144